

Accurate study guides, High passing rate! Testhorse provides update free of charge in one year!

## Exam : HP0-J56

# Title: 3PAR Solutions AdvancedService and Support

## Version : Demo

1. Which rules must be followed with regard to disk type, size, and speed in a V400 drive magazine?

- A. Disks must all be of the same type size, and speed
- B. Disk sizes may be mixed, but rotation speed must be the same.
- C. Disks of the same type are required, although disk speeds can be mixed.
- D. Disks of any type, size, and speed can be mixed.

#### Answer: D

2.Which steps are performed before adding new hardware components to an existing HP 3PAR system? (Select two)

- A. Preparing an electrostatic discharge safe (ESD) environment
- B. Ensuring power supplies are available
- C. Upgrading the current environment to the latest In Form OS
- D. Checking the health of the system
- E. Updating the service processor

#### Answer: A,B

- 3. Which statement is true regarding HP 3PAR Remote Copy?
- A. Supports 4:1 ratio using asynchronous periodic mode
- B. Initial copy will not replicate zeroes
- C. Requires a separate Windows 2008 server to initiate failover
- D. RCIP supports up to 450-500 MB/s

#### Answer: A

4.What is the lowest level of HP 3PAR service that provides seven day a week, round-the-clock, four-hour onsite response?

- A. Mission Critical
- B. Support Plus 24
- C. Proactive24
- D. AR Array Base Warranty
- Answer: C
- 5. How are the ports numbered on a V400 or V800 PCI adapter?
- A. From left to right
- B. From bottom to top
- C. From right to left
- D. From top to bottom
- Answer: A

6. Identify the valid mode used in Adaptive Optimization policies?

- A. Capacity
- B. Availability
- C. Ownership
- D. Balanced
- Answer: D

7.Which customer requirement would prompt an EVA recommendation instead of a 3PAR recommendation?

- A. Federation
- B. High availability
- C. Fibre Channel
- D. Journal-based asynchronous replication

#### Answer: C

- 8.Which statement is true when comparing F400 and V400 controller nodes?
- A. Control memory has increased from 6 GB to 16 GB.
- B. PCI slots have increased from 6 to 12 per controller node.
- C. Data memory has increased from 6 GB to 16 GB
- D. Maximum battery life has reduced from 25 to 15 minutes when fully charged.

#### Answer: A

9.Your customer wants an HP 3PAR V400 with four controllers and four DC4 chassis.

What is the minimum number of maps per chassis?

- A. Three mags per DC4
- B. Four mags per DC4
- C. Two mags per DC4
- D. One mag per DC4

#### Answer: B

#### 10.HOTSPOT

Match the correct value with the 3PAR specification.

Maximum number of read/write copies per base volume	•
Number of controllers in a T800 minimum configuration	·
Number of built-in IP Remote Copy ports in V800 maximum configuration	
Chunklet size (MB) in V400 Storage System	•

Maximum number of read/write copies per base volume


Number of controllers in a T800 minimum configuration


Number of built-in IP Remote Copy ports in V800 maximum configuration


Chunklet size (MB) in V400 Storage System


Answer:













### Maximum number of read/write copies per base volume



Number of controllers in a T800 minimum configuration



Number of built-in IP Remote Copy ports in V800 maximum configuration

Chunklet size (MB) in V400 Storage System

